

Inspection Photos

February 1, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 335359

Location Name: KELL-66S93W/35NENW

Inspection Document #: 702801210

Garfield County, CO

NENW Section 35 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 1. Photo taken from the north shows an overview of the location.

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 2. Photo shows the eroding cut slope at the north of the location.



Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 3. Photo shows rill erosion occurring on the cut slope at the north of the location.

Inspection Photos

Location Name: KELL-66S93W/35NENW

Location ID: 335359



Photo 4. Photos show exposed roots of grazed or uprooted perennial grasses.



COLORADO

Oil & Gas Conservation
Commission


Department of Natural Resources

Inspection Number: 702801210

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 5. Photos show two (2) risers which appear to be associated with a plugged and abandoned well and decommissioned flowline and separator.



Inspection Number: 702801210



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



2/1/23
+39.488260,-107.745260
42° NE



Photo 6. Photos show production areas.

Inspection Photos
Location Name: KELL-66S93W/35NENW
Location ID: 335359



Photo 7. Photo shows an example of interim areas.

