



00572706

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

☒ NOTICE OF UNSATISFACTORY INSPECTION

☐ NOTICE OF SATISFACTORY INSPECTION

API No. 05- 061 - 6107

LEASE NAME: DAWSON #6

LOCATION: SWNE8-19S-45W

OPERATOR: WESTERN O.P.

DATE: 10-27-95

INSPECTOR: R. Vansickle

Insp. Type: ID Insp. Status: TA PA: Y N Pass/Fail: P F Viol.: Y N NOV: Y N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210)	None.	✓
Pits (Reserve/Production) (Rule 902, 903, 904)	None.	
Fences (Rule 604.C.(3), 1003.A)	None.	
Tank Battery Equipment (Rule 604)	No equip.	✓
Fire Walls/Berms/Dikes (Rule 604)	N/A.	
General Housekeeping (Rule 603.G)	Good.	
Spills (Oil/Water) (Rule 908)	None.	
Bradenhead (Rule 207)	—	
Drilling Well/Workover (Rule 315)	—	
Surface Rehabilitation (Rule 317)	—	
Miscellaneous	—	

CORRECTIVE ACTION REQUIRED: MITS Produce or Plug

Date Corrective Action Required By: 4-15-96

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

BOB VANSICKLE 719/336-2843