



COLORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

Oct. 03 1997



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 061 - 6107		LEASE NAME: Dawson #6	
LOCATION: SWNE 8-195-45W		OPERATOR: WESTERN O.P.	
DATE: 8-25-97		INSPECTOR: L. VanSickle	
Insp. Type: CA	Insp. Status: PA	PA: Y (N)	Pass/Fail: (P) F Viol.: Y (N) NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	Ret. set @ 2335'. String in & pump 10 B.W. 2 1/2 B.W. @ 200 PSI. Mix & pump 2000 gal, lost 2 B.W. of disp. press. up to 300 PSI. String out & spot 2 sk. on ret. COOH 7/27	✓
Miscellaneous	fts of tbg to 1508'. Balance 25 sk plug & COOH tbg. SD for night.	✓

CORRECTIVE ACTION REQUIRED: None

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site