



00572701

# COLORADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT

ACT. 03 1997  
C

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	
API No. 05-06) - 6107	LEASE NAME: DAWSON #6
LOCATION: SWNE 8-19S-45W	OPERATOR: WESTERN OP.
DATE: 8-27-97	INSPECTOR: R. Janslickle
Insp. Type: CA	Insp. Status: PA
PA: Y (N)	Pass/Fail: P (F)
Viol.: Y (N)	NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)		
<b>Fences</b> (Rule 604.C.(3), 1003.A)		
<b>Tank Battery Equipment</b> (Rule 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 604)		
<b>General Housekeeping</b> (Rule 603.G)		
<b>Spills (Oil/Water)</b> (Rule 908)		
<b>Bradenhead</b> (Rule 207)	Tagged plug @ 1247'	
<b>Drilling Well/Workover</b> (Rule 315)	Spotted 2 plugs @ 1508' yesterday. Perf @ 1137' set ret. @ 1100'. Pump 120sk plug thru ret. Perf @ 220' 194' cooh w/ ret. Plug. Hook up & establish circulation thru perfor.	
<b>Surface Rehabilitation</b> (Rule 317)		
<b>Miscellaneous</b>	Mil & pump 100sk.	

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By: \_\_\_\_\_ Date Remedied: \_\_\_\_\_

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.