

Inspection Photos

2/3/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #440705

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



Photo 1: Photos 1-2 taken from the south end of the Location, and provide an overview of the Location from west, northwest, northeast to east. Photos also show areas of the current working pad between the wells, and the tank battery facility that are not reasonably needed for production operations, and require interim reclamation.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #440705



February 3, 2023



February 3, 2023

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



Photo 3: Photos taken from the northwest end of the Location, facing east and south. Photos show areas of the current working pad between the wells, and the tank battery facility that are not reasonably needed for production operations, and require interim reclamation.



Photo 4: 2022 Google Earth Aerial image. Photos show areas of the current working pad between the wells, and the tank battery facility that are not reasonably needed for production operations, and require interim reclamation.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



February 3, 2023



February 3, 2023

Photo 5: Photo example showing BMPs to stabilize the Location, and to minimize tracking and off-site sediment transport (Gravel, compaction, etc...) show signs of degradation; Ground was frozen at time of inspection, and Location was largely covered with snow, however BMPs that were observable appear to be insufficient. Maintenance advised.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #440705



February 3, 2023



February 3, 2023

Photo 6: Photos show tank signage/labeling is either missing, or inaccurate.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #440705



February 3, 2023



February 3, 2023

Photo 7: Photos show tank signage/labeling is either missing, or inaccurate.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #440705



February 3, 2023



February 3, 2023

Photo 8: Photos example showing current reclamation areas; areas that were visible appear to be predominantly Undesirable Plant Species, such as *Salsola* sp., and *Kochia*- unclear if areas are progressing towards 1003 standards, and a followup inspection will be conducted to determine compliance with 1003 Rules.