

Inspection Photos

February 1, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334931

Location Name: BENZEL-66S93W/35SESE

Inspection Document #: 702801214

Garfield County, CO

SESE Section 35 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BENZEL-66S93W/35SESE
Location ID: 334931



Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: BENZEL-66S93W/35SESE
Location ID: 334931



Photo 2. Photos show production areas.

Inspection Photos
Location Name: BENZEL-66S93W/35SESE
Location ID: 334931



Photo 3. Photo shows an example of interim areas. Perennial grasses appear established.

