

Inspection Photos

February 1, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334961

Location Name: BENZEL-67S93W/1SWSW

Inspection Document #: 702801220

Garfield County, CO

SWSW Section 1 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BENZEL-67S93W/1SWSW
Location ID: 334961



Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: BENZEL-67S93W/1SWSW
Location ID: 334961



Photo 2. Photo shows old injection line equipment/debris.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801220

Inspection Photos
Location Name: BENZEL-67S93W/1SWSW
Location ID: 334961




Photo 3. Photos show production areas.

Inspection Photos
Location Name: BENZEL-67S93W/1SWSW
Location ID: 334961



Photo 4. Photo shows an example of interim areas. Perennial grasses appear established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801220