

Inspection Photos
Location Name: State Antelope K-O-1HNB
Location ID: 431198



Photo 1 – Wellhead



Photo 2 – Compressor

Inspection Photos
Location Name: State Antelope K-O-1HNB
Location ID: 431198



Photo 3 – Unmarked Risers



Photo 4 – Unmarked Risers

Inspection Photos
Location Name: State Antelope K-O-1HNB
Location ID: 431198



Photo 5 – Unmarked Riser



Photo 6 – Unmarked Riser

Inspection Photos
Location Name: State Antelope K-O-1HNB
Location ID: 431198



Photo 7 – Unmarked Risers



Photo 8 – Oily Waste

Inspection Photos
Location Name: State Antelope K-O-1HNB
Location ID: 431198



Photo 9 – Wildlife Netting



Photo 10 – Unmarked Riser

Inspection Photos
Location Name: State Antelope K-O-1HNB
Location ID: 431198



Photo 11 – Unmarked Riser



Photo 12 – Unmarked Riser – Middle Riser and 1" at Berm

Inspection Photos
Location Name: State Antelope K-O-1HNB
Location ID: 431198



Photo 13 – Separators



Photo 14 – Tank Battery

Inspection Photos
Location Name: State Antelope K-O-1HNB
Location ID: 431198



Photo 15 – Tank Battery Signs



Photo 16 – Labels

Inspection Photos
Location Name: State Antelope K-O-1HNB
Location ID: 431198



Photo 15 – Tank Battery Signs



Photo 16 – Labels