

Inspection Photos

February 1, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334899

Location Name: BENZEL-66S93W/36NESW

Inspection Document #: 702801224

Garfield County, CO

NESW Section 36 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BENZEL-66S93W/36NESW
Location ID: 334899



Photo 1. Photo taken from the south shows an overview of the location. Interim areas (foreground appear vegetated with perennial grasses).

Inspection Photos
Location Name: BENZEL-66S93W/36NESW
Location ID: 334899



Photo 2. Photo shows two (2) risers which appear to be associated with a plugged and abandoned well and decommissioned flowline.

Inspection Photos
Location Name: BENZEL-66S93W/36NESW
Location ID: 334899



Photo 3. Photos show excavations at separators/flowline (left) and well API # 045-08178 (right).



Inspection Photos
Location Name: BENZEL-66S93W/36NESW
Location ID: 334899



Photo 4. Photos show stockpiled soil at separators/flowline (left) and well API 045-08178 (right).



Inspection Photos
Location Name: BENZEL-66S93W/36NESW
Location ID: 334899



Photo 5. Photos show production areas.