

# Inspection Photos

2/3/2023

Operator: CAERUS PICEANCE LLC #10456

Location #334733

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334733



**Photo 1:** Photos examples showing various holes/tears observed at the tank battery's secondary containment.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #334733



**Photo 2:** Unused pipe equipment stored on south end of the Location