

Inspection Photos

API: 071-08414

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08414 | Date: 1/3/2023

Inspection Photos



Photo 1. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08414 | Date: 1/3/2023

Inspection Photos



Photo 2. Facing toward the production equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08414 | Date: 1/3/2023

Inspection Photos



Photo 3. Facing toward the fill slope of the location. This area appear to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08414 | Date: 1/3/2023