

# Inspection Photos

API: 071-09496

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09496 | Date: 1/3/2023

## Inspection Photos



**Photo 1.** Facing toward the wellsite. Stained soil has been cleaned up at wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09496 | Date: 1/3/2023

## Inspection Photos



**Photo 2.** It appears leak was repaired at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09496 | Date: 1/3/2023

## Inspection Photos



**Photo 3.** There is a new fence installed around the lined pit.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09496 | Date: 1/3/2023