

Inspection Photos

API: 071-09604

Operator: OGRIS OPERATING LLC

Inspection Date: 1/3/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09604 | Date: 1/3/2023

Inspection Photos



Photo 1. Facing toward the wellsite. There is a new fence installed around the lined pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09604 | Date: 1/3/2023

Inspection Photos



Photo 2. Stained soils have been cleaned up at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09604 | Date: 1/3/2023