

Inspection Photos

2/3/2023

Operator: CAERUS PICEANCE LLC #10456

Location #334625

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334625



Photo 1: Location Overview.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334625



February 3, 2023



February 3, 2023

Photo 2: Additional methanol tank on location (left). Active wells on Location (right).



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location #334625



Photo 3: Photo shows tank battery facility on Location. Photo shows signage per Rule 605.e is missing.

