

Inspection Photos

2/3/2023

Operator: TEP ROCKY MOUNTAIN LLC #
96850

Location #159652
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location #159652



Photo 1:. Photos provide an overview of the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location #159652



Photo 2: Photo example showing incorrect label information observed on the Separator equipment.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location #159652



February 3, 2023

Photo 3: Haybales and livestock paneling observed improperly stored on the north end of the Location; The storage, or placement of materials, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location #159652



February 3, 2023



February 3, 2023

Photo 4: Photo shows Undesirable Plant Species / Weed debris on the west end of the Location.