

# Inspection Photos

February 1, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334967

Location Name: BENZEL-66S93W/36SESW

Inspection Document #: 702801226

Garfield County, CO

SESW Section 36 T6S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334967




**Photo 1.** Photo taken from the west shows an overview of the location.



## Inspection Photos

Location Name: BENZEL-66S93W/36SESW

Location ID: 334967



**Photo 2.** Photo shows a tank which appears pitted, rusted and/or potentially compromised.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801226



Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334967



**Photo 3.** Photos show production areas.

Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334967



**Photo 4.** Photo shows an example of interim areas. Perennial grasses appear established.

