

Inspection Photos

February 1, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334944

Location Name: BENZEL-66S93W/36SESW

Inspection Document #: 702801227

Garfield County, CO

SESW Section 36 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BENZEL-66S93W/36SESW
Location ID: 334944



Photo 1. Photo taken from the south shows an overview of the location.



Inspection Photos
Location Name: BENZEL-66S93W/36SESW
Location ID: 334944



Photo 2. Photo show staining at the separator for well API #045-07462.



Inspection Photos
Location Name: BENZEL-66S93W/36SESW
Location ID: 334944



2/1/23
+39.477911,-107.727092
33° NE



Photo 3. Photos show production areas.

Inspection Photos
Location Name: BENZEL-66S93W/36SESW
Location ID: 334944



2/1/23
+39.477801,-107.727147
95° E

Photo 4. Photo shows an example of interim areas. Perennial grasses appear established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801227