

# Inspection Photos

February 1, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334829

Location Name: BENZEL-66S93W/36SESW

Inspection Document #: 702801230

Garfield County, CO

SESW Section 36 T6S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334829



**Photo 1.** Photo taken from the north shows an overview of the location.



Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334829



**Photo 2.** Photo shows piping lacking wildlife protection devices.





Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334829



2/1/23  
+39.477956,-107.716726  
88° E



**Photo 3.** Photos show production areas.

Inspection Photos  
Location Name: BENZEL-66S93W/36SESW  
Location ID: 334829



**Photo 4.** Photo shows an example of interim areas.

