

Final Reclamation and Stormwater Inspection

Date: 02/06/2023

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320555

Inspection Document #: 696105716

Adams County, CO

NWSE Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Mula-61S66W 26 NWSE
Location ID: 320555



Photo 1. Facing south from the reclaimed access road entrance. Photo illustrates that the operator appears to have completed the corrective action from the previous inspection and managed the undesirable vegetation that was observed onsite.

Inspection Photos
Location Name: Mula-61S66W 26 NWSE
Location ID: 320555



Photo 2. Facing south, see comments in Photo 1.

Inspection Photos
Location Name: Mula-61S66W 26 NWSE
Location ID: 320555



Photo 3. Facing west, see comments in Photo 1.

Inspection Photos
Location Name: Mula-61S66W 26 NWSE
Location ID: 320555



Photo 4. Facing north, see comments in Photo 1.