

# Final Reclamation and Stormwater Inspection

Date: 02/06/2023

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 320530

Inspection Document #: 696105718

Adams County, CO

SENW Section 26 T1S R66W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Leech 22-26  
Location ID: 320530



**Photo 1.** Facing north from the former access road entrance to the well. It appears the operator has reclaimed the former access road by removing the gravel/road base and performing revegetation activities.

Inspection Photos  
Location Name: Leech 22-26  
Location ID: 320530



**Photo 2.** Facing northwest from the former access road. It appears the operator has performed the corrective action and recontoured the former access road to reflect natural/reference area topography and performed revegetation activities.

Inspection Photos  
Location Name: Leech 22-26  
Location ID: 320530



**Photo 3.** Facing south from the former well location; see comments in Photos 1 & 2.