

# Final Reclamation and Stormwater Inspection

Date: 02/06/2023

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 320550

Inspection Document #: 696105722

Adams County, CO

SESW Section 26 T1S R66W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Leech 24-26  
Location ID: 320550



**Photo 1.** Facing south at location, It appears the operator has managed the undesirable vegetation identified in the previous inspection.

Inspection Photos  
Location Name: Leech 24-26  
Location ID: 320550



**Photo 2.** Facing west at location, see comments in Photo 1.