

Final Reclamation and Stormwater Inspection

Date: 02/06/2023

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 320606

Inspection Document #: 696105726

Adams County, CO

NESE Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Maul 43-26
Location ID: 320606



Photo 1. Facing southwest from location's entrance. It appears the operator has performed the corrective action identified in previous inspections.

Inspection Photos
Location Name: Maul 43-26
Location ID: 320606



Photo 2. Facing west, see comments in Photo 1.

Inspection Photos
Location Name: Maul 43-26
Location ID: 320606



Photo 3. Facing west, see comments in Photo 1.