

# Final Reclamation and Stormwater Inspection

Date: 02/06/2023

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 320561

Inspection Document #: 696105728

Adams County, CO

SESE Section 26 T1S R66W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Maul 44-26  
Location ID: 320561



**Photo 1.** Facing west from the location's entrance. It appears the operator has performed the corrective actions identified in the previous inspections and has managed the location for undesirable vegetation.

Inspection Photos  
Location Name: Maul 44-26  
Location ID: 320561



**Photo 2.** Facing west, see comments in Photo 1.



Inspection Photos  
Location Name: Maul 44-26  
Location ID: 320561



**Photo 3.** Facing west, see comments in Photo 1.