

Final Reclamation and Stormwater Inspection

Date: 02/06/2023

Operator: EXTRACTION OIL & GAS - 10459

Location ID: 320472

Inspection Document #: 696105730

Adams County, CO

SE Section 26 T1S R66W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Maul 2
Location ID: 320472



Photo 1. Facing north at the well location. It appears the operator has performed the previous corrective action and has managed the location for undesirable vegetation.

Inspection Photos
Location Name: Maul 2
Location ID: 320472



Photo 2. Facing south from the former access road. See comments in Photo 1.