

Environmental Inspection

February 3, 2023

Operator: D09 ENERGY LLC - #10706

Location ID: 436007

Spill ID: 483729

Inspection Document #: 690900231

Jackson County, CO

NENW Section 32 T8N R80W

Alex Fischer

Environmental Supervisor - Western Colorado, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Grizzly 3-32H
Location ID: 436007



Photo 1. Sign at tank battery.

Inspection Photos
Location Name: Grizzly 3-32H
Location ID: 436007



Photo 2. Photo taken from the NW corner of the tank battery. Crews have removed ice and pea gravel from on top of the secondary containment liner. Multiple tears are noted in the liner with shovels directly on the liner.



Photo 3. Photo taken from the east side of the tank battery. Crews have removed ice and pea gravel from on top of the secondary containment liner. Multiple tears are noted in the liner.

Inspection Photos
Location Name: Grizzly 3-32H
Location ID: 436007



Photo 4. Photo taken from the NE corner of the tank battery. Crews have removed ice and pea gravel from on top of the secondary containment liner. Multiple tears are noted in the liner.



Photo 5. Photo taken from the north side of the tank battery. Crews have removed ice and pea gravel from on top of the secondary containment liner. Multiple tears are noted in the liner.