



**COLORADO OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT**

NOV 09 1995 C

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
API No. 05- 061 - 5144	LEASE NAME: HARRISON #2
LOCATION: NENE9-195-45W	OPERATOR: WESTERN OP.
DATE: 10-19-95	INSPECTOR: R. Vansickle
Insp. Type: ID	Insp. Status: TA
PA: Y    N	Pass/Fail: <u>P</u> F
	Viol.: <u>Y</u> N
	NOV: Y    N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)	↘	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)	None	
<b>Fences</b> (Rule 604.C.(3), 1003.A)	None	
<b>Tank Battery Equipment</b> (Rule 604)	None	
<b>Fire Walls/Berms/Dikes</b> (Rule 604)	N/A	
<b>General Housekeeping</b> (Rule 603.G)	OK	
<b>Spills (Oil/Water)</b> (Rule 908)	None	
<b>Bradenhead</b> (Rule 207)	—	
<b>Drilling Well/Workover</b> (Rule 315)	—	
<b>Surface Rehabilitation</b> (Rule 317)	—	
<b>Miscellaneous</b>	No equip, csq swedged to 2".	✓

**CORRECTIVE ACTION REQUIRED:** MIT, Produce or Plug.

Date Corrective Action Required By: 4-15-96      Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File    Green - Operator    Canary - Well Site

BOB VANSICKLE 719/336-2843