

Inspection Photos
Location Name: State Antelope 11-2HZ
Location ID: 422681



Photo 1 – Tank Battery




Photo 2 – Tank Battery Signs

Inspection Photos
Location Name: State Antelope 11-2HZ
Location ID: 422681



Photo 3 – Separators



Photo 4 – Water Tank Labels

Inspection Photos
Location Name: State Antelope 11-2HZ
Location ID: 422681




Photo 5 – Unmarked Risers at North Separator



Photo 6 – Wellhead