

Interim Reclamation and Stormwater Inspection

Date: 02/10/2023

Operator: VERDAD RESOURCES LLC - 10651

Location ID: 432694

Inspection Document #: 696105732

Weld County, CO

NENE Section 35 T9N R60W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Shull Pad
Location ID: 432694



Photo 1. Facing west from the location's entrance. Photo illustrates the operator has managed the undesirable vegetation previously identified in inspection (Doc #696105694). The operator shall continue to manage the location for undesirable vegetation and debris in the future.

Inspection Photos
Location Name: Shull Pad
Location ID: 432694



Photo 2. Facing north near the wellhead. The operator has removed the leaking tank from location and cleaned the stained soil. The other equipment pictured will be reinstalled after a nearby well is fracked, per 02/10/2023 phone call with Operator.

Inspection Photos
Location Name: Shull Pad
Location ID: 432694



Photo 3. Facing west at compressor station. Photo illustrates that no wildlife protection devices (e.g. snow fence or similar) were installed when the antifreeze spill was observed during this inspection. Per 02/10/2023 phone call, Operator stated that they installed and took down snow fence after the antifreeze spill was cleaned up the first time (~01/24/2023). Operator will now have to reinstall wildlife protection device until spill is cleaned up.

Inspection Photos
Location Name: Shull Pad
Location ID: 432694



Photo 4. Close up photo of antifreeze spill observed on 02/10/2023.

Inspection Photos
Location Name: Shull Pad
Location ID: 432694



Photo 5. See comments in Photo 4.