

# Inspection Photos

February 7, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335076

Location Name: CLOUGH-66S94W/29SEnw

Inspection Document #: 702801244

Garfield County, CO

SEnw Section 29 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CLOUGH-66S94W/29SENW  
Location ID: 335076



**Photo 1.** Photos show an overview of the location to the west (left) and southeast (right).





Inspection Photos  
Location Name: CLOUGH-66S94W/29SENW  
Location ID: 335076




**Photo 2.** Photos show stained soil beneath chemical injection equipment.





Inspection Photos  
Location Name: CLOUGH-66S94W/29SENW  
Location ID: 335076



**Photo 3.** Photo shows leaking chemical injection equipment.