DENÁLI
303.390.5200
ROAD
CLOSED

CLOSE OUT

Well Name(s):	MCVEY 1	Date:	1/24/2023
Supervisor: Rig / Close Out	JASON GIBBS // MIKE COURIER	Engineer:	TJ HANNEMAN
Phone Number:	720-532-5537 // 307-690-7771	Project Type:	RE ENTRY P&A
Production Foreman:	DILLON HEIN	Rig #:	ENSIGN 122
Operator:	CVITAS RESOURCES	Start Date:	1/13/2023
Location Access:	ACCESS FROM 56TH	End Date:	1/18/2023
DIRECTIONS:	IMBODEN AND 56TH AVE W 6.0 MI, S .1 MI, E .1 MI INTO		

API:	05-001-05050	SURFACE:	WORKING WITH DEVELOPER	GPS:	39.796403 - 104.69459	COUNTY:	ADAMS	AFE: Codes:	23075 AFE // 8306.240 BILLING CODE

	YES/NO	Comments		YES/NO	Comments
Monitor:	YES	SHOT WITH LDAR AT TIME OF CUT AND CAP	Pictures:	YES	N,E,S,W & AERIAL
Migration:	NO		Automation:	NO	
Cement to Surface:	YES	TOPPED OFF 1/23/2023	Perimeter Fence:	NO	
Form 27 Approved:	N/A	NO FORM 27 REQUIRED	Chemical	NO	
Cut and Cap Scheduled:	YES	PERFORMED 1/23/23 // 12' BELOW GRADE 5335 CUT ELEVATION	Location Cleaned	YES	
Re Entry Necessary:	NO		Notify Production:	YES	W/ THIS NOTICE.

REPORT

TOOK AERIAL PHOTOS OF 56TH AVE TO CONCLUDE THAT WE HAD NO MUD TRACKING. WILL ATTACH PHOTOS THAT SHOW JUST MOISTURE. I DID SEND A STREET SWEEPER BY FOR A COUPLE MORE PASSES AFTER PHOTOS TAKEN AND ALL EQUIPMENT IS OFF LOCATION. NO RECLEMATION NEEDED, DEVELOPER WILL MOVE DIRT AFTER DEPARTURE