

# Inspection Photos

API: 073-06300

Operator: MULL DRILLING COMPANY INC

Inspection Date: 1/7/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06300 | Date: 1/7/2023

## Inspection Photos



**Photo 1.** Facing northwest toward the wellsite.



## Inspection Photos



**Photo 2.** The shed is in disrepair and the panel has fallen off.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06300 | Date: 1/7/2023

## Inspection Photos



**Photo 3.** Facing southwest toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06300 | Date: 1/7/2023