

Inspection Photos

API: 073-06303

Operator: MULL DRILLING COMPANY INC

Inspection Date: 1/7/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06303 | Date: 1/7/2023

Inspection Photos




Photo 1. Center of the location facing north. The perennial vegetation has not re-established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 1/7/2023

Inspection Photos



Photo 2. Center of the location facing south. The perennial vegetation has not re-established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 1/7/2023

Inspection Photos



Photo 3. Facing southwest at the location. This area is approximately 80x80' with minimal vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 1/7/2023

Inspection Photos



Photo 4. Facing toward the groundcover at the location which shows insufficient vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 1/7/2023

Inspection Photos




Photo 5. Facing northwest toward the surrounding undisturbed area which consists of a uniform native vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 1/7/2023