

Inspection Photos

API: 073-06485

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/7/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06485 | Date: 1/7/2023

Inspection Photos



Photo 1. Facing southwest toward the location. The gate between the two wood post is down and the fence is not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06485 | Date: 1/7/2023

Inspection Photos



Photo 2. Facing southwest toward the location. The perennial vegetation has not established and most of the location is bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06485 | Date: 1/7/2023

Inspection Photos




Photo 3. Facing south overlooking the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06485 | Date: 1/7/2023

Inspection Photos



Photo 4. Facing down toward the surrounding undisturbed reference area which has a uniform native vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06485 | Date: 1/7/2023