

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8959 From entrance to location.



Photo #8960 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8961 From entrance to location.



Photo #8962 Loves truck stop from wellheads.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8963 Loves truck stop from wellheads.



Photo #8964 Loves truck stop from wellheads.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8966 Loves truck stop from wellheads.



Photo #896 Loves truck stop from wellheads.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8968 Location lacks stabilization.



Photo #8969 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8969 Location lacks stabilization.



Photo #8970 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8972 Location lacks stabilization.



Photo #8973 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8979 Insufficient tracking BMP at entrance to location.



Photo #8981 Multiple places with trash next to access road that appears to be from Loves construction.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8989 Multiple places with trash next to access road that appears to be from Loves construction.



Photo #890 Construction supplies.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8991 Multiple places with trash next to access road that appears to be from Loves construction.



Photo #8992 Multiple places with trash next to access road that appears to be from Loves construction.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC T & T Assoc. LTD /PA 21

Location ID: 420224



Photo #8991 Multiple places with trash next to access road that appears to be from Loves construction.



Photo #8992 Multiple places with trash next to access road that appears to be from Loves construction.