

# Inspection Photos

February 7, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 324090

Location Name: CLOUGH-66S94W/29NENW

Inspection Document #: 702801252

Garfield County, CO

NENW Section 29 T6S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CLOUGH-66S94W/29NENW  
Location ID: 324090



**Photo 1.** Photo taken from the entrance shows an overview of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801252

Inspection Photos  
Location Name: CLOUGH-66S94W/29NENW  
Location ID: 324090



2/7/23  
07.915323  
348° N



Photo 2. Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801252

Inspection Photos  
Location Name: CLOUGH-66S94W/29NENW  
Location ID: 324090



**Photo 3.** Photo shows an example of the interim areas. Introduced perennial grasses and native shrubs appear established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801252