

Inspection Photos

February 7, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335371

Location Name: CLOUGH-66S94W/29NENW

Inspection Document #: 702801254

Garfield County, CO

NENW Section 29 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CLOUGH-66S94W/29NENW
Location ID: 335371



Photo 1. Photo taken from the entrance shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801254

Inspection Photos
Location Name: CLOUGH-66S94W/29NENW
Location ID: 335371



Photo 2. Photo shows an example of the interim areas. Introduced perennial grasses appear established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801254

Inspection Photos
Location Name: CLOUGH-66S94W/29NENW
Location ID: 335371



Photo 3. Photo shows the access road. It appears gravel has been added at the entrance to the east of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801254