

Inspection Photos

February 7, 2023

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 335141

Location Name: WILLIAMS-66S94W/29NWNW

Inspection Document #: 702801258

Garfield County, CO

NWNW Section 29 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: WILLIAMS-66S94W/29NWNW

Location ID: 335141



Photo 1. Photo taken from the entrance shows an overview of the lower/southern (left) and upper/northern (right) portions of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801258

Inspection Photos
Location Name: WILLIAMS-66S94W/29NWNW
Location ID: 335141



2/7/23
-107.917952
337° NW



Photo 2. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801258

Inspection Photos
Location Name: WILLIAMS-66S94W/29NWNW
Location ID: 335141



Photo 3. Photo shows four (4) tamarisk plants (List B Noxious) in the northern interim area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801258

Inspection Photos
Location Name: WILLIAMS-66S94W/29NWNW
Location ID: 335141



Photo 4. Photos show examples of the interim areas to the south (left) and north (right). Native perennial grasses and shrubs appear established.

