

# Inspection Photos

February 13, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334930

Location Name: CEDAR SPRINGS RANCH-67S93W/2NESW

Inspection Document #: 702801260

Garfield County, CO

NESW Section 2 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

## Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/2NESW

Location ID: 334930



**Photo 1.** Photos show a flowline riser which appears to be associated with a flowline for plugged and abandoned well API #045-07641.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801260



## Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/2NESW

Location ID: 334930



**Photo 2.** Photo shows well API # 045-07803.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801260