

Inspection Photos

API: 071-06426

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/14/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06426 | Date: 2/14/2023

Inspection Photos



Photo 1. Facing north along the access road. There has been additional roadbase applied to the road and crowned.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06426 | Date: 2/14/2023

Inspection Photos



Photo 2. Facing north along the access road. The roadside which was eroded has been repaired but there is no BMP's to prevent erosion from reoccurring (e.g. check dams, riprap, culvert ect).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06426 | Date: 2/14/2023

Inspection Photos



Photo 3. Facing back south toward the access road. This long stretch of road has no roadside BMPs to prevent erosion from reoccurring. Red arrow points to stormwater flow which will occur down the roadside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06426 | Date: 2/14/2023

Inspection Photos



Photo 4. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06426 | Date: 2/14/2023