

Inspection Photos

February 13, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334602

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Inspection Document #: 702801264

Garfield County, CO

NWSE Section 11 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE

Location ID: 334602



Photo 1. Photos show produced water/condensate tank # 81396 appears to have spilled from the top. Stained gravel observed in secondary containment below the spill (right).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801264

Inspection Photos
Location Name: CEDAR SPRINGS RANCH-67S93W/11NWSE
Location ID: 334602



Photo 2. Photo shows a cap has been installed on separator piping per previous corrective action.