

Final Reclamation Inspection

September 23, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 331942

Inspection Document #: 708000009

Weld County, CO

SESE Section 8 3N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LDS #20-8
Location ID: 331942



Photo 1. Google Earth aerial imagery taken 6/2017 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle) and approximate flowlines (red line).

Inspection Photos
Location Name: LDS #20-8
Location ID: 331942




Photo 2. COGCC Online Map aerial imagery 2019 with related wells (red dot), subject well (blue dot), tank battery (near north east corner) and flowlines (black lines). Flowline abandonment/removal not submitted.

Inspection Photos
Location Name: LDS #20-8
Location ID: 331942




Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates harvested crop on and around the well location (red circle) and flowline (red line). Tank Battery is addressed in Location 330106 report.

Inspection Photos
Location Name: LDS #20-8
Location ID: 331942




Photo 4. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates harvested crop field on and around the well location (red circle). Access road was shared with agriculture. Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.

Inspection Photos
Location Name: LDS #20-8
Location ID: 331942




Photo 5. Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates harvested crop on approximate flowline (red line). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.