

# Final Reclamation Inspection

October 5, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 329194

Inspection Document #: 708000036

Weld County, CO

NWNE Section 14 4N64W 6

Kasen Huwa  
Reclamation Contractor, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STINAR \*14-2(1), C \*14-28D  
Location ID: 329194



**Photo 1.** Google Earth aerial imagery taken 9/2013 during active operations. Photo illustrates the well locations (red circle) and tank battery (red rectangle).

Inspection Photos  
Location Name: STINAR \*14-2(1), C \*14-28D  
Location ID: 329194




Photo 2. COGCC Online Map aerial imagery 2019 with subjected wells (red dots).

Inspection Photos  
Location Name: STINAR \*14-2(1), C \*14-28D  
Location ID: 329194



**Photo 3.** Orthomosaic drone aerial imagery taken from 200 ft (Sept 2022). Illustrates harvested crop on and around the well locations (red circle). Tank Battery is addressed in Location 323230 report.