

Final Reclamation Inspection

September 27, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 306539

Inspection Document #: 708000070

Weld County, CO

NENW Section 4 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Google Earth aerial imagery taken 7/2019 during active operations. Photo illustrates the well location (red circle), tank battery (red square), flowline (red line), and well location access road (white arrow).

Inspection Photos
Location Name: CONNELL C #4-29
Location ID: 306539



Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (northeast corner) and flowlines (black lines).

Inspection Photos
Location Name: CONNELL C #4-29
Location ID: 306539



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle), flowlines and access road (white arrow). Red line is approximate flowlines. Tank battery is addressed in Location 329878 report.

Inspection Photos
Location Name: CONNELL C #4-29
Location ID: 306539



Photo 4. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle). Ground is fallow, so another inspection is required when crop is actively growing. Access road is not apparent.