

Final Reclamation Inspection

September 27, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 319182

Inspection Document #: 708000085

Weld County, CO

NWNW Section 4 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CONNELL #1
Location ID: 319182



Photo 1. Google Earth aerial imagery taken 7/2019 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and approximate flowlines (red line).

Inspection Photos
Location Name: CONNELL #1
Location ID: 319182



Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related well (red dot), tank battery (north center) and flowlines (black lines).

Inspection Photos
Location Name: CONNELL #1
Location ID: 319182




Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle), tank battery (north), flowlines, and access road. Red line is approximate flowlines and blue is approximate access road.

Inspection Photos
Location Name: CONNELL #1
Location ID: 319182



Photo 4. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.



Photo 5. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates no growth on the tank battery location (red rectangle).