

Final Reclamation Inspection

September 27, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 323668

Inspection Document #: 708000100

Weld County, CO

NESE Section 3 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: KISSLER #3-2
Location ID: 323668




Photo 1. Google Earth aerial imagery taken 2/2020 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and flowline (red line).

Inspection Photos
Location Name: KISSLER #3-2
Location ID: 323668




Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related well (red dot), tank battery (northwest corner) and flowlines (black lines). Flowline abandonment form has not been submitted.

Inspection Photos
Location Name: KISSLER #3-2
Location ID: 323668



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle). Tank battery is addressed in Location 329783 report.

Inspection Photos
Location Name: KISSLER #3-2
Location ID: 323668



Photo 4. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle). Some bare soil is visible however it appears to be less than 5% or 10%. Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.