

Final Reclamation Inspection

September 23, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 330145

Inspection Document #: 708000118

Weld County, CO

NESW Section 17 3N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LDS D *17-20
Location ID: 330145



Photo 1. Google Earth aerial imagery taken 8/2018 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and approximate flowlines (red line).

Inspection Photos
Location Name: LDS D *17-20
Location ID: 330145




Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (northwest corner), and flowlines (black lines).

Inspection Photos
Location Name: LDS D *17-20
Location ID: 330145



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Spt. 2022). Illustrates growth on and around the well location (red circle), flowlines (red lines) and tank battery (red rectangle).

Inspection Photos
Location Name: LDS D *17-20
Location ID: 330145



Photo 4. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.

N →



Photo 5. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the tank battery. Equipment remains (blue rectangle) on tank battery location.