

Final Reclamation Inspection

September 27, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 332012

Inspection Document #: 708000137

Weld County, CO

SWNW Section 4 4N64W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CONNELL C #4-5
Location ID: 332012



Photo 1. Google Earth aerial imagery taken 7/2019 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), access road (white arrow), and approximate flowlines (red line).

Inspection Photos
Location Name: CONNELL C #4-5
Location ID: 332012



Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (north center) and flowlines (black lines). Flowline abandonment form has not been submitted.

Inspection Photos
Location Name: CONNELL C #4-5
Location ID: 332012



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle), flowlines (red lines) and access road (white arrow). Red line is approximate flowlines. Tank Battery is addressed in Location 319182 report.

Inspection Photos
Location Name: CONNELL C #4-5
Location ID: 332012



Photo 4. Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates lack of growth on and around the well location (red circle). Appears to have bare soil. Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.