

# Final Reclamation Inspection

October 07, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -  
47120

Location ID: 332111

Inspection Document #: 708000193

Weld County, CO

SWSE Section 4 2N65W 6

Kasen Huwa  
Reclamation Contractor, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission


Department of Natural Resources

Inspection Photos  
Location Name: MOSER \*15-4  
Location ID: 332111



**Photo 1.** Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and flowline (red line).

Inspection Photos  
Location Name: MOSER \*15-4  
Location ID: 332111



**Photo 2.** COGCC Online Map aerial imagery 2019 with related wells (red dots), subject well (blue dot), tank battery (near southeast corner) and flowlines (black lines).

Inspection Photos  
Location Name: MOSER \*15-4  
Location ID: 332111



**Photo 3.** Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle) and flowline (red line). Access road is not visible. Tank Battery is addressed in Location 305754 report.

Inspection Photos  
Location Name: MOSER \*15-4  
Location ID: 332111



**Photo 4.** Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.

Inspection Photos  
Location Name: MOSER \*15-4  
Location ID: 332111



**Photo 6.** Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates mainly rangeland growth with some harvested crop on and around the flowline. Located mainly on the edge of the field.