

Final Reclamation Inspection

October 07, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 336489

Inspection Document #: 708000206

Weld County, CO

SWSW Section 33 3N65W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CANNON X *04-30D
Location ID: 336489



Photo 1. Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and flowline (red line).

Inspection Photos
Location Name: CANNON X *04-30D
Location ID: 336489




Photo 2. COGCC Online Map aerial imagery 2019 with related wells (red dots), subject well (blue dot), tank battery (near southwest corner) and flowlines (black lines).

Inspection Photos
Location Name: CANNON X *04-30D
Location ID: 336489



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates rangeland growth on and around the well location (red circle), flowline (red line), tank battery (red rectangle) and access road (blue line). Tank battery area and access road still visible, so not full rangeland coverage.




Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates rangeland growth on and around the well location (red circle) and access road (blue line). Comparable to surrounding area.

Inspection Photos
Location Name: CANNON X *04-30D
Location ID: 336489



Photo 5. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates some rangeland growth on and around the tank battery (red rectangle) and access road (blue line). Tank battery is removed.