

Final Reclamation Inspection

October 07, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 329678

Inspection Document #: 708000210

Weld County, CO

NWSW Section 33 3N65W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources




Photo 1. Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and flowline (red line).



Inspection Photos
Location Name: UPRC *33-12J5
Location ID: 329678




Photo 2. COGCC Online Map aerial imagery 2019 with related wells (red dots), subject well (blue dot), tank battery (near northwest corner) and flowlines (black lines).



Inspection Photos
Location Name: UPRC *33-12J5
Location ID: 329678



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates rangeland on and around the well location (red circle), flowline (red line), and access road (above blue line). Tank battery is still has equipment remaining. Access road is still visible.

Inspection Photos
Location Name: UPRC *33-12J5
Location ID: 329678



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates rangeland growth on and around the well location (red circle) that is comparable to surrounding area. Access road (blue line) is barely visible in an agricultural field.

Inspection Photos
Location Name: UPRC *33-12J5
Location ID: 329678



Photo 5. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates equipment remaining on tank battery (red rectangle).



Photo 6. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates lack of full rangeland growth on and around the access road (blue line).